## RECEIVED

Revised 10/03

DUE DATE

DIST.

BERARDINI, J. H

CROCKETT, G. A. DECK, C. A. DEGENHART, K. R.

DIETER, T. J. DIETERLE, S. E

FERRERA, D. W

GIACOMINI. J. J

HIETT, S. B.

LINDSAY, D LONG, J. W.

NAGEL R. E. NORTH, K. PARKER, A. M. RODGERS, A. D. SHELTON, D. C. SPEARS, M. S.

TUOR, N. R

WIENERK

Freiboth C

NUSHa S

COR, CONTROL ADMN, RECORD PATS/130

LYLE, J. L. MARTINEZ, L. A

BROOKS, I

ACTION

CORRES. CONTROL INCOMING LTR NO.

288 OCT 15 A 9 39

## CONTROL STATE OF COLORADO

00954 RF03

Bill Owens, Governor

Douglas H. Benevento, Executive Director

Dedicated to protecting and improving the health and environment of the people of Colorado

4300 Cherry Creek Dr. S. Denver, Colorado 80246-1530 Phone (303) 692-2000

8100 Lowry Blvd. Denver, Colorado 80230-6928

Laboratory and Radiation Services Division

TDD Line (303) 691-7700 (303) 692-3090

Located in Glendale, Colorado http://www.cdphe.state.co.us Colorado Department of Public Health and Environment

October 9, 2003

Mr. Joe Legare

Acting Assistant Manager for Environment and Stewardship U.S. Department of Energy, Rocky Flats Field Office 10808 Highway 93, Unit A Golden, CO 80403-8200

RE: Closeout Report for Building 334

Dear Mr. Legare:

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has reviewed the Closeout Report for Building 334, dated October 6, 2003. We appreciate being provided this Closeout Report for our information.

As we have previously requested, Closeout Reports should identify all removal activity and include a map of the facility identifying the structures involved, those removed, and the location of remaining infrastructure and its condition. Infrastructure includes all remaining materials and their location, and includes slabs, piers, footings, water pipes, gas lines, electrical conduits, drain lines, PWLs, sewer lines, etc. These maps are necessary for possible ER and/or future stewardship concerns. The discussion provided does not specifically address the infrastructure removed or remaining. It can only be assumed that the entire slab has been removed, and that inground utilities remain at the locations identified on the figure provided. It is also assumed, since not discussed, that this remaining infrastructure has been removed to below three feet of the final grade for this area, and that the sewer lines were not removed to the main line as indicated in the Facility Disposition RSOP, which is supposed to be followed for all facilities. As such, we would appreciate being provided a revised Closeout Report for B334 addressing these concerns.

If you have any questions regarding this correspondence please contact me at (303) 692-3367 or David Kruchek

at (303) 692-3328.

B 1 - 1/ - 1/1 - -

Reviewed for Addressee Corres. Control RFP

Corres. Control RFP

10/15/03 20 Date By

Ref. Ltr. #

DOE ORDER #

Sincerely,

Steven H. Gunderson RFCA Project Coordinator

> Steve Tower, DOE Tim Rehder, EPA Karen Wiemelt, KH

David Abelson, RFCLOG

Cameron Freiboth, KH Dave Shelton, KH Steve Nesta, KH

Administrative Records Building T130G